

Inch to Millimeter Conversion Chart

| INCH | | METRIC | |
|---------|---------|--------|-------|
| 2 in. | 1-31/32 | 51 | 50 mm |
| | 1-15/16 | 49 | |
| 1-7/8 | 1-29/32 | 48 | 45 |
| | 1-27/32 | 47 | |
| 1-13/16 | 1-25/32 | 46 | 40 |
| | 1-23/32 | 44 | |
| 1-3/4 | 1-11/16 | 43 | 35 |
| | 1-21/32 | 42 | |
| 1-5/8 | 1-19/32 | 41 | 30 |
| | 1-17/32 | 39 | |
| 1-1/2 | 1-15/32 | 38 | 25 |
| | 1-7/16 | 37 | |
| 1-3/8 | 1-13/32 | 36 | 20 |
| | 1-11/32 | 34 | |
| 1-5/16 | 1-9/32 | 33 | 15 |
| | 1-7/32 | 32 | |
| 1-1/4 | 1-5/32 | 31 | 10 |
| | 1-3/32 | 29 | |
| 1-3/16 | 1-3/32 | 28 | 5 |
| | 1-1/32 | 27 | |
| 1-1/8 | 31/32 | 26 | 0 mm |
| | 15/16 | 24 | |
| 1 in. | 29/32 | 23 | 0 mm |
| | 27/32 | 22 | |
| 7/8 | 13/16 | 21 | 0 mm |
| | 25/32 | 19 | |
| 3/4 | 11/16 | 18 | 0 mm |
| | 21/32 | 17 | |
| 5/8 | 9/16 | 16 | 0 mm |
| | 17/32 | 14 | |
| 1/2 | 15/32 | 13 | 0 mm |
| | 7/16 | 12 | |
| 3/8 | 13/32 | 11 | 0 mm |
| | 11/32 | 9 | |
| 5/16 | 9/32 | 8 | 0 mm |
| | 7/32 | 7 | |
| 1/4 | 3/16 | 6 | 0 mm |
| | 5/32 | 4 | |
| 1/8 | 3/32 | 3 | 0 mm |
| | 1/32 | 2 | |
| 0 in. | | 1 | 0 mm |